

UNIFOSA Corp.
Technical Support Team
Firmware Release Notes

Model: SASIII to SASIII /SATA3 16/24 CHL. JBOD
For: EP-2126J1/JD1-SCSC, EP-3166J1/JD1-SCSC, EP-2246J/JD-SCSC, EP-4246J/JD-SCSC, EN-2126JSC-xxx, EN3166JSC-xxx Series.

Important notes:

- 1. Upgrade firmware: sas3xfwxxx.fw**

	Last Version	New Version
Version	0.0.23	0.0.26
Release Date	JUL 20,2018	OCT 18,2019
New	<ol style="list-style-type: none"> 1. Add the CLI Nick Name setting. 	<ol style="list-style-type: none"> 1. EICMSNT24C02ATG (ATMEL AT24C02N) change to EICMSN00LC02MIG (Microchip 24LC02BT-I/SN), Change EEPROM delay time from 5ms to 11ms.
Fixed	<ol style="list-style-type: none"> 1. After modifying the fan level, fans 3 fans 4 have no fixed speed problem. 	
Modification	<ol style="list-style-type: none"> 1. Modify the slot & temp ses string and cancel the SLOT 01 space. 2. Modify page 1 message RltbProclD, NumProc. 3. The Routing type is changed from "S" to "T". 4. Temperature & voltage detection retry is changed from 3 times to 10 times, once every 4 seconds, and the "0xFF" error code is ignored. 	<ol style="list-style-type: none"> 1. Change the SES Report order. 2. Enable VPD Page 80.
Removed		